



## COMPLETED WORK

### PARKING

Sl. No	Description of item	Photograph
1	Providing Plastering for celings 10MM thick in C.M 1:4	
2	Providing Plastering for internal walls 15MM thick in C.M 1:5	

**FIRST FLOOR**

1



Supplying and fixing teakwood windows with frame 125 X 65mm and glazed shutters with 4mm glass and stainless mesh shutters





2

Teakwood louvered ventilators



3	Applying 2 coats of Putty, 1 coat Primer and 2 coats of plastic emulsion painting over ceilings and walls	
<b>Second Floor</b>		
1	Supplying and fixing teakwood windows with frame 125 X65 mm and glazed shutters with 4 mm glass and stainless mesh shutters.	

2	Teakwood louvered ventilators	
3	Applying 2 coats of putty, 1 coat primer and 2 coats of plastic emulsion painting over ceilings and walls	

Internal services

1

Add 5% for internal electrical wiring on total value of work ( Parking 1<sup>st</sup> ,2<sup>nd</sup> , 3<sup>rd</sup> Floors)

